



*Working with Oregonians  
to ensure safe building  
construction while  
supporting a positive  
business climate.*

## **Errata for the 2010 Oregon Structural Specialty Code, first printing**

**Contact:** Richard Rogers, Structural Program Chief, 503-378-4472 or [richard.rogers@state.or.us](mailto:richard.rogers@state.or.us)  
Shane Sumption, Fire, Life-Safety / ADA, 503-378-4635 or [shane.r.sumption@state.or.us](mailto:shane.r.sumption@state.or.us)

---

~~Strikethrough~~ text represents deleted language.

Underlined text represents added language.

---

*Note: The 2010 Oregon Structural Specialty Code as printed by the International Codes Council, incorporates the International Codes Council's errata for the first printing of the 2009 International Building Code.*  
<http://www.iccsafe.org/cs/codes/Errata/2009IBC-complete.pdf>

1. Page 400, Delete Section 1613.7.8 in its entirety: ~~Amendment to ASCE 7-05, Section 13.5.6.2.2~~  
Item e, "suspended ceilings" in Seismic Design Categories D through F. Amend as follows:
  - e. ~~For ceiling areas exceeding 1,000 ft<sup>2</sup>, horizontal restraint of the ceiling to the structural system shall be provided.~~

